






TDK Corporation

HHM1715E1

Gawo la Nambala:
Wopanga / Chinthu:
Mafotokozedwe Akatundu
Datasheets:
Mkhalidwe wa RoHS
Chombo Chochokera
Njira Yopereker


HHM1715E1
TDK Corporation
BALUN 3.3GHZ-3.9GHZ 50/100 0603
 [HHM1715E1.pdf](#)
 Kutsogolera / RoHS Kumvera
Hong Kong
DHL/Fedex/TNT/UPS/EMS



Chithunzi chingakhale choyimira. Onani ndondomeko zogwiritsira ntchito mankhwala.

PEMPHO LA QUOTATION













Mafotokozedwe a HHM1715E1

GAWO LA NAMBALA	HHM1715E1
WOPANGA	TDK Corporation
KUFOTOKOZERA	BALUN 3.3GHZ-3.9GHZ 50/100 0603
MKHALIDWE WOPANDA UFULU / MKHALIDWE WA ROHS	Kutsogolera / RoHS Kumvera
TSAMBA LAZAMBIRI	 HHM1715E1.pdf
MNDANDANDA	HHM
BWERERANI KUTAYIKA (MIN)	10dB
KUSIYANA KWA PHASE	180° ±15°
KUPAKA	Cut Tape (CT)
PHUKUSI / MLANDUWU	0603 (1608 Metric)
MAINA ENA	445-3995-1
MTUNDU WOKWERA	Surface Mount
MPHUNO YOPANDA CHISOKONEZO (MSL)	1 (Unlimited)
NTHAWI YOTSOGOLERA YOYENERA	12 Weeks
MKHALIDWE WOPANDA UFULU / MKHALIDWE WA ROHS	Lead free / RoHS Compliant
KUTAYA KULOWA (MAX)	1.0dB
KUTAYA MTIMA - KUSAYENERERA / KUSAMALA	50 / 100 Ohm
CHIWERENGERO CHAFUPIPAFUPI	3.3GHz ~ 3.9GHz
KUFOTOKOZEDWA KWAMBIRI	RF Balun 3.3GHz ~ 3.9GHz 50 / 100 Ohm 0603 (1608 Metric)

Matanthauzo okhudzana

TDK Corporation HHM1715E1	Wogulitsa HHM1715E1	Wothandizira HHM1715E1
Mtengo wa HHM1715E1	Zithunzi za HHM1715E1	Chithunzi cha HHM1715E1
Datasheet ya PDF ya HHM1715E1	HHM1715E1 Tsitsa Datasheet	Datasheet ya HHM1715E1
HHM1715E1 Stock	Gulani HHM1715E1	Gulani TDK Corporation HHM1715E1
TDK Corporation HHM1715E1	Wothandizira TDK Corporation	Wopatsa TDK Corporation
TDK Corporation HHM1715E1		

Zogwirizana

 <p>HHM1727D1 Opanga: TDK Corporation Kufotokozera: BALUN 3.3GHZ-3.9GHZ 50/50 0603 Zilipo: Out stock RFQ</p>	 <p>HHM17165A1 Opanga: TDK Corporation Kufotokozera: BALUN 2.4GHZ-2.8GHZ 50/50 0603 Zilipo: Out stock RFQ</p>
 <p>HHM17166A1 Opanga: TDK Corporation Kufotokozera: BALUN 1.9GHZ-2.3GHZ 50/50 0603 Zilipo: Out stock RFQ</p>	 <p>HHM17153A2 Opanga: TDK Corporation Kufotokozera: BALUN 698MHZ-894MHZ 50/50 0603 Zilipo: Out stock RFQ</p>
 <p>HHM17168B1 Opanga: TDK Corporation Kufotokozera: BALUN 3.4GHZ-3.8GHZ 50/50 0603 Zilipo: Out stock RFQ</p>	 <p>HHM17144A1 Opanga: TDK Corporation Kufotokozera: BALUN 791MHZ-960MHZ 50/100 0603 Zilipo: Out stock RFQ</p>
 <p>HHM17146A1 Opanga: TDK Corporation Kufotokozera: BALUN 1.92GHZ-2.17GHZ 50/50 0603 Zilipo: Out stock RFQ</p>	 <p>HHM17139B1 Opanga: TDK Corporation Kufotokozera: BALUN 2.4GHZ-2.5GHZ 50/50 0603 Zilipo: Out stock RFQ</p>
 <p>HHM17152A1 Opanga: TDK Corporation Kufotokozera: BALUN 698MHZ-894MHZ 50/100 0603 Zilipo: Out stock RFQ</p>	 <p>HHM1726N1 Opanga: TDK Corporation Kufotokozera: BALUN 824MHZ-915MHZ 50/100 0603 Zilipo: Out stock RFQ</p>
 <p>HHM1726P1 Opanga: TDK Corporation Kufotokozera: BALUN 880MHZ-960MHZ 50/100 0603 Zilipo: Out stock RFQ</p>	 <p>HHM17139B2 Opanga: TDK Corporation Kufotokozera: BALUN 2.4GHZ-2.6GHZ 50/50 0603 Zilipo: Out stock RFQ</p>