

N/A

LMK00304SQX/NOPB

Gawo la Nambala: LMK00304SQX/NOPB
 Wopanga / Chinthu: N/A
 Mafotokozedwe Akatundu: IC CLK BUFFER 3:5 3.1GHZ 32WQFN
 Datasheets:
 Mkhalidwe wa RoHS: Kutsogolera / RoHS Kumvera
 Chombo Chochokera: Hong Kong
 Njira Yoperekeru: DHL/Fedex/TNT/UPS/EMS



[PEMPHO LA QUOTATION](#)

Chithunzi chingakhale choyimira. Onani ndondomeko zogwiritsira ntchito mankhwala.

Mafotokozedwe a LMK00304SQX/NOPB

GAWO LA NAMBALA	LMK00304SQX/NOPB
WOPANGA	N/A
KUFOTOKOZERA	IC CLK BUFFER 3:5 3.1GHZ 32WQFN
MKHALIDWE WOPANDA UFULU / MKHALIDWE WA ROHS	Kutsogolera / RoHS Kumvera
TSAMBA LAZAMBIRI	
MPHAMVU - ZOPEREKA	3.15 V ~ 3.45 V
LEMBANI	Fanout Buffer (Distribution), Multiplexer, Translator
PHUKUSI LA CHIPANGIZO CHOTHANDIZIRA	32-WQFN (5x5)
MNDANDANDA	-
KUGWIRIZANA - KULOWETSA: KUCHOKERA	3:5
KUPAKA	Tape & Reel (TR)
PHUKUSI / MLANDUWU	32-WFQFN Exposed Pad
ZOTSATIRA	HCSL, LVCMOS, LVDS, LVPECL
KUTENTHA KWAMBIRI	-40°C ~ 85°C
CHIWERENGERO CHA MAULENDO	1
MTUNDU WOKWERA	Surface Mount
MPHUNO YOPANDA CHISOKONEZO (MSL)	3 (168 Hours)
MKHALIDWE WOPANDA UFULU / MKHALIDWE WA ROHS	Lead free / RoHS Compliant
KULOWETSA	CML, HCSL, HSTL, LVDS, LVPECL, SSTL, Crystal
MAULENDO - MAX	3.1GHz
KUSIYANITSA - KULOWETSA: KUTULUKA	Yes/Yes
KUFOTOKOZEDWA KWAMBIRI	Clock Fanout Buffer (Distribution), Multiplexer, Translator IC 3:5 3.1GHz 32-WFQFN Exposed Pad
CHIGAWO CHOYAMBIRA	LMK00304

Matanthauzo okhudzana

LMK00304SQX/NOPB	Wogulitsa LMK00304SQX/NOPB	Wothandizira LMK00304SQX/NOPB
Mtengo wa LMK00304SQX/NOPB	Zithunzi za LMK00304SQX/NOPB	Chithunzi cha LMK00304SQX/NOPB
Datasheet ya PDF ya LMK00304SQX/NOPB	LMK00304SQX/NOPB Tsitsa Datasheet	Datasheet ya LMK00304SQX/NOPB
LMK00304SQX/NOPB Stock	Gulani LMK00304SQX/NOPB	Gulani LMK00304SQX/NOPB
LMK00304SQX/NOPB	Wothandizira	Wopatsa

Zogwirizana

<p>LMK00306SQ/NOPB Opanga: N/A Kufotokozera: IC CLK BUFFER 3:7 3.1GHZ 36WQFN Zilipo: 15141 pcs RFQ</p>	<p>LMK00301SQ/NOPB Opanga: N/A Kufotokozera: IC CLK BUFFER 3:10 3.1GHZ 48WQFN Zilipo: 16276 pcs RFQ</p>
<p>LMK00306SQE/NOPB Opanga: N/A Kufotokozera: IC CLK BUFFER 3:7 3.1GHZ 36WQFN Zilipo: 15141 pcs RFQ</p>	<p>LMK00308SQ/NOPB Opanga: N/A Kufotokozera: IC CLK BUFFER 3:9 3.1GHZ 40WQFN Zilipo: 16225 pcs RFQ</p>
<p>LMK00308EVM/NOPB Opanga: N/A Kufotokozera: BOARD EVAL FOR LMK00308 Zilipo: 337 pcs RFQ</p>	<p>LMK00304SQ/NOPB Opanga: N/A Kufotokozera: IC CLK BUFFER 3:5 3.1GHZ 32WQFN Zilipo: 24218 pcs RFQ</p>
<p>LMK00304SQE/NOPB Opanga: N/A Kufotokozera: IC CLK BUFFER 3:5 3.1GHZ 32WQFN Zilipo: 16840 pcs RFQ</p>	<p>LMK00306EVM/NOPB Opanga: N/A Kufotokozera: BOARD EVAL FOR LMK00306 Zilipo: 409 pcs RFQ</p>
<p>LMK00301SQX/NOPB Opanga: N/A Kufotokozera: IC CLK BUFFER 3:10 3.1GHZ 48WQFN Zilipo: 17670 pcs RFQ</p>	<p>LMK00304EVM/NOPB Opanga: N/A Kufotokozera: BOARD EVAL FOR LMK00304 Zilipo: 425 pcs RFQ</p>
<p>LMK00301SQE/NOPB Opanga: N/A Kufotokozera: IC CLK BUFFER 3:10 3.1GHZ 48WQFN Zilipo: 10236 pcs RFQ</p>	<p>LMK00306SQX/NOPB Opanga: N/A Kufotokozera: IC CLK BUFFER 3:7 3.1GHZ 36WQFN Zilipo: 19578 pcs RFQ</p>