



Pulse Electronics Corporation

TM1062FCA1

Gawo la Nambala:
Wopanga / Chinthu:
Mafotokozedwe Akatundu

Datasheets:

Mkhalidwe wa RoHS
Chombo Chochokera
Njira Yopereker

TM1062FCA1
Pulse Electronics Corporation
TRANSCIEVER PBC
[PDF](#) 1. TM1062FCA1.pdf
[PDF](#) 2. TM1062FCA1.pdf
Funsani zofufuza / RoHS zosagwirizana
Hong Kong
DHL/Fedex/TNT/UPS/EMS

PEMPHO LA QUOTATION

Chithunzi chingakhale choyimira. Onani ndondomeko zogwiritsira ntchito mankhwala.

Mafotokozedwe a TM1062FCA1

GAWO LA NAMBALA	TM1062FCA1
WOPANGA	Pulse Electronics Corporation
KUFOTOKOZERA	TRANSCIEVER PBC
MKHALIDWE WOPANDA UFULU / MKHALIDWE WA ROHS	Funsani zofufuza / RoHS zosagwirizana
TSAMBA LAZAMBIRI	PDF 1. TM1062FCA1.pdf PDF 2. TM1062FCA1.pdf
MPHAMVU - ZOPEREKA	5V
LEMBANI	Transceiver
PHUKUSI LA CHIPANGIZO CHOTHANDIZIRA	Module
MNDANDANDA	Copperhead™
PULOGALAMU	IEEE 1394B
PHUKUSI / MLANDUWU	28-SMD Module
KUTENTHA KWAMBIRI	-55°C ~ 125°C
CHIWERENGERO CHA MADALAIVALA / OPEZERA	1/1
MTUNDU WOKWERA	Surface Mount
MPHUNO YOPANDA CHISOKONEZO (MSL)	3 (168 Hours)
NTHAWI YOTSOGOLERA YOYENERA	19 Weeks
MKHALIDWE WOPANDA UFULU / MKHALIDWE WA ROHS	Request inventory verification / RoHS non-compliant
DUPLEX	-
KUFOTOKOZEDWA KWAMBIRI	1/1 Transceiver IEEE 1394B Module
NDONDOMEKO YA DATA	1.062Gbps

Matanthauzo okhudzana

Pulse Electronics Corporation TM1062FCA1	Wogulitsa TM1062FCA1	Wothandizira TM1062FCA1
Mtengo wa TM1062FCA1	Zithunzi za TM1062FCA1	Chithunzi cha TM1062FCA1
Datasheet ya PDF ya TM1062FCA1	TM1062FCA1 Tsitsa Datasheet	Datasheet ya TM1062FCA1
TM1062FCA1 Stock	Gulani TM1062FCA1	Gulani Pulse Electronics Corporation TM1062FCA1
Pulse Electronics Corporation TM1062FCA1	Wothandizira Pulse Electronics Corporation	Wopatsa Pulse Electronics Corporation
Pulse Electronics Corporation TM1062FCA1	Pulse A Technitrol Company TM1062FCA1	Pulse TM1062FCA1

Zogwirizana

<p>TM1062DUXB Opanga: Pulse Electronics Corporation Kufotokozera: TRANSCIEVER PBC Zilipo: Out stock RFQ</p>	<p>TM1062HSB1 Opanga: Pulse Electronics Corporation Kufotokozera: TRANSCIEVER TM1062HSB1 PBC Zilipo: Out stock RFQ</p>
<p>TM1062DVB2 Opanga: Pulse Electronics Corporation Kufotokozera: TRANSCIEVER PBC Zilipo: Out stock RFQ</p>	<p>TM1062DUB2 Opanga: Pulse Electronics Corporation Kufotokozera: TRANSCIEVER PBC Zilipo: Out stock RFQ</p>
<p>TM1062FUB Opanga: Pulse Electronics Corporation Kufotokozera: TRANSCIEVER MODULE PBC Zilipo: Out stock RFQ</p>	<p>TM1062DVB Opanga: Pulse Electronics Corporation Kufotokozera: TRANSCIEVER MODULE PBC Zilipo: Out stock RFQ</p>
<p>TM1062FSB2 Opanga: Pulse Electronics Corporation Kufotokozera: TRANSCIEVER MODULE PBC Zilipo: Out stock RFQ</p>	<p>TM1062FCA2 Opanga: Pulse Electronics Corporation Kufotokozera: TRANSCIEVER PBC Zilipo: Out stock RFQ</p>
<p>TM1062DUA1 Opanga: Pulse Electronics Corporation Kufotokozera: TRANSCIEVER PBC Zilipo: Out stock RFQ</p>	<p>TM1062DVA1 Opanga: Pulse Electronics Corporation Kufotokozera: MIL-AERO Zilipo: Out stock RFQ</p>
<p>TM1062FSB Opanga: Pulse Electronics Corporation Kufotokozera: TRANSCIEVER MODULE PBC Zilipo: Out stock RFQ</p>	<p>TM1062FSA Opanga: Pulse Electronics Corporation Kufotokozera: TRANSCIEVER PBC Zilipo: Out stock RFQ</p>

